

Table ENG-2. - Construction Materials

Bedford County, Virginia

The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.00 to 0.99. The smaller the value, the greater the limitation.

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
1B:							
Altavista	80	Fair		Poor		Fair	
		Low content of organic matter	0.13	Low strength	0.00	Depth to saturated zone	0.53
		Too acid	0.21	Depth to saturated zone	0.53	Too acid	0.76
Wet spots	5	Not Rated		Not Rated		Not Rated	
2D:							
Ashe	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.05	Slope	0.50	Rock fragments	0.00
		Low content of organic matter	0.13			Depth to bedrock	0.05
2E:							
Ashe	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.05	Slope	0.00	Rock fragments	0.00
		Low content of organic matter	0.13			Depth to bedrock	0.05
3C:							
Berks	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Rock fragments	0.00
		Depth to bedrock	0.01	Cobble content	0.82	Depth to bedrock	0.01
		Too acid	0.50			Slope	0.63
3D:							
Berks	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.01	Slope	0.50	Rock fragments	0.00
		Too acid	0.50	Cobble content	0.82	Depth to bedrock	0.01
3E:							
Berks	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.01	Slope	0.00	Rock fragments	0.00
		Too acid	0.50	Cobble content	0.82	Depth to bedrock	0.01
4B:							
Braddock	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Too acid	0.60
		Too acid	0.50				

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
4C:							
Braddock	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Too acid	0.60
		Too acid	0.50			Slope	0.63
4D:							
Braddock	85	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.50	Too Clayey	0.00
		Too acid	0.50	Shrink-swell	0.89	Too acid	0.60
5B:							
Braddock	85	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Too acid	0.60
		Too acid	0.50				
5C:							
Braddock	85	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Too acid	0.60
		Too acid	0.50			Slope	0.63
6C:							
Braddock	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Too acid	0.60
		Too acid	0.50			Slope	0.63
6D:							
Braddock	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.50	Too Clayey	0.00
		Too acid	0.50	Shrink-swell	0.89	Too acid	0.60
7B:							
Cecil	70	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.02			Too acid	0.88
		Too acid	0.32				

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
7C:							
Cecil	70	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.02			Slope	0.63
		Too acid	0.32			Too acid	0.88
8A:							
Chewacla	75	Fair		Poor		Poor	
		Too acid	0.68	Depth to saturated zone	0.00	Depth to saturated zone	0.00
Wet spots	5	Not Rated		Not Rated		Not Rated	
9B:							
Cullen	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.87		
		Too acid	0.74				
9C:							
Cullen	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.87	Slope	0.63
		Too acid	0.74				
9D:							
Cullen	70	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.50	Too Clayey	0.00
		Too acid	0.74	Shrink-swell	0.87		
10D:							
Dekalb	80	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.50	Rock fragments	0.00
		Depth to bedrock	0.16	Cobble content	0.74	Depth to bedrock	0.16
10E:							
Dekalb	80	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.00	Rock fragments	0.00
		Depth to bedrock	0.16	Cobble content	0.74	Depth to bedrock	0.16
11C:							

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
11C:							
Edneytown	80	Fair		Poor		Fair	
		Low content of organic matter	0.13	Low strength	0.00	Rock fragments	0.50
		Too acid	0.32	Depth to bedrock	0.00	Slope	0.63
		Droughty	>0.99			Too acid	0.88
11D:							
Edneytown	80	Fair		Poor		Poor	
		Low content of organic matter	0.13	Low strength	0.00	Slope	0.00
		Too acid	0.32	Depth to bedrock	0.00	Rock fragments	0.50
		Droughty	>0.99	Slope	0.50	Too acid	0.88
11E:							
Edneytown	75	Fair		Poor		Poor	
		Low content of organic matter	0.13	Slope	0.00	Slope	0.00
		Too acid	0.32	Low strength	0.00	Rock fragments	0.50
		Droughty	>0.99	Depth to bedrock	0.00	Too acid	0.88
12C:							
Edneytown	80	Fair		Poor		Fair	
		Low content of organic matter	0.13	Low strength	0.00	Rock fragments	0.50
		Too acid	0.32	Depth to bedrock	0.00	Slope	0.63
		Droughty	>0.99			Too acid	0.88
12D:							
Edneytown	80	Fair		Poor		Poor	
		Low content of organic matter	0.13	Low strength	0.00	Slope	0.00
		Too acid	0.32	Depth to bedrock	0.00	Rock fragments	0.50
		Droughty	>0.99	Slope	0.50	Too acid	0.88
12E:							
Edneytown	80	Fair		Poor		Poor	
		Low content of organic matter	0.13	Slope	0.00	Slope	0.00
		Too acid	0.32	Low strength	0.00	Rock fragments	0.50
		Droughty	>0.99	Depth to bedrock	0.00	Too acid	0.88
13D:							
Edneyville	70	Fair		Poor		Poor	
		Too acid	0.54	Depth to bedrock	0.00	Slope	0.00
		Low content of organic matter	0.68	Slope	0.50	Hard to reclaim	0.13
		Droughty	0.89	Cobble content	0.94	Rock fragments	0.13
13E:							

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
13E:							
Edneyville	70	Fair		Poor		Poor	
		Too acid	0.54	Slope	0.00	Slope	0.00
		Low content of organic matter	0.68	Depth to bedrock	0.00	Hard to reclaim	0.13
		Droughty	0.89	Cobble content	0.94	Rock fragments	0.13
14C:							
Grover	70	Fair		Good		Fair	
		Low content of organic matter	0.13			Slope	0.63
		Too acid	0.54			Too acid	0.98
14D:							
Grover	70	Fair		Fair		Poor	
		Low content of organic matter	0.13	Slope	0.50	Slope	0.00
		Too acid	0.54			Too acid	0.98
14E:							
Grover	70	Fair		Poor		Poor	
		Low content of organic matter	0.13	Slope	0.00	Slope	0.00
		Too acid	0.54			Too acid	0.98
15C:							
Gunstock	80	Fair		Poor		Fair	
		Low content of organic matter	0.13	Depth to bedrock	0.00	Too Clayey	0.55
		Too acid	0.50	Low strength	0.00	Slope	0.63
		Droughty	0.52	Shrink-swell	0.87	Depth to bedrock	0.84
15D:							
Gunstock	80	Fair		Poor		Poor	
		Low content of organic matter	0.13	Depth to bedrock	0.00	Slope	0.00
		Too acid	0.50	Low strength	0.00	Too Clayey	0.55
		Droughty	0.52	Slope	0.50	Depth to bedrock	0.84
15E:							
Gunstock	80	Fair		Poor		Poor	
		Low content of organic matter	0.13	Depth to bedrock	0.00	Slope	0.00
		Too acid	0.50	Slope	0.00	Too Clayey	0.55
		Droughty	0.52	Low strength	0.00	Depth to bedrock	0.84
16B:							

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
16B:							
Hayesville	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Too acid	0.21			Too acid	0.76
		Low content of organic matter	0.88				
16C:							
Hayesville	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Too acid	0.21			Slope	0.63
		Low content of organic matter	0.88			Too acid	0.76
16D:							
Hayesville	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Too acid	0.21	Slope	0.50	Too Clayey	0.00
		Low content of organic matter	0.88			Too acid	0.76
16E:							
Hayesville	75	Poor		Poor		Poor	
		Too clayey	0.00	Slope	0.00	Slope	0.00
		Too acid	0.21	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.88			Too acid	0.76
17C:							
Hayesville	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Too acid	0.21			Slope	0.63
		Low content of organic matter	0.88			Too acid	0.76
17D:							
Hayesville	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Too acid	0.21	Slope	0.50	Too Clayey	0.00
		Low content of organic matter	0.88			Too acid	0.76
17E:							
Hayesville	80	Poor		Poor		Poor	
		Too clayey	0.00	Slope	0.00	Slope	0.00
		Too acid	0.21	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.88			Too acid	0.76
18B:							

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
18B:							
Helena	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Too acid	0.12	Depth to saturated zone	0.14	Depth to saturated zone	0.14
		Low content of organic matter	0.13	Shrink-swell	0.16	Too acid	0.60
18C:							
Helena	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Too acid	0.12	Depth to saturated zone	0.14	Depth to saturated zone	0.14
		Low content of organic matter	0.13	Shrink-swell	0.16	Too acid	0.60
19B:							
Iredell	70	Poor		Poor		Poor	
		Too clayey	0.00	Depth to saturated zone	0.00	Too Clayey	0.00
		Low content of organic matter	0.02	Shrink-swell	0.00	Depth to saturated zone	0.00
		Too acid	0.97				
19C:							
Iredell	70	Poor		Poor		Poor	
		Too clayey	0.00	Depth to saturated zone	0.00	Too Clayey	0.00
		Low content of organic matter	0.02	Shrink-swell	0.00	Depth to saturated zone	0.00
		Too acid	0.97			Slope	0.63
20B:							
Laidig	80	Fair		Poor		Fair	
		Droughty	0.11	Depth to cemented pan	0.00	Too acid	0.60
		Too acid	0.12	Low strength	0.00	Depth to saturated zone	0.89
		Low content of organic matter	0.13	Depth to saturated zone	0.89	Depth to cemented pan	0.94
20C:							
Laidig	75	Fair		Poor		Fair	
		Droughty	0.11	Depth to cemented pan	0.00	Too acid	0.60
		Too acid	0.12	Low strength	0.00	Slope	0.63
		Low content of organic matter	0.13	Depth to saturated zone	0.89	Depth to saturated zone	0.89
21D3:							
Madison	75	Poor		Fair		Poor	
		Too clayey	0.00	Slope	0.50	Slope	0.00
		Low content of organic matter	0.02			Too Clayey	0.00
		Too acid	0.50			Too acid	0.88

21E3:

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
21E3:							
Madison	70	Poor		Poor		Poor	
		Too clayey	0.00	Slope	0.00	Slope	0.00
		Low content of organic matter	0.02			Too Clayey	0.00
		Too acid	0.50			Too acid	0.88
22D:							
Manteo	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.00	Slope	0.50	Depth to bedrock	0.00
		Low content of organic matter	0.13			Rock fragments	0.00
22E:							
Manteo	70	Poor		Poor		Poor	
		Droughty	0.00	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.00	Slope	0.00	Depth to bedrock	0.00
		Low content of organic matter	0.13			Rock fragments	0.00
23B:							
Mattaponi	85	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.87	Too acid	0.88
		Too acid	0.50				
23C:							
Mattaponi	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.87	Slope	0.63
		Too acid	0.50			Too acid	0.88
24B:							
Mecklenburg	70	Fair		Good		Good	
		Low content of organic matter	0.02				
24C:							
Mecklenburg	70	Fair		Good		Fair	
		Low content of organic matter	0.02			Slope	0.63
24D:							
Mecklenburg	75	Fair		Fair		Poor	
		Low content of organic matter	0.02	Slope	0.50	Slope	0.00

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
25C:							
Nason	70	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.39	Hard to reclaim	0.50
		Too acid	0.50	Shrink-swell	0.97	Slope	0.63
25D:							
Nason	70	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.39	Too Clayey	0.00
		Too acid	0.50	Slope	0.50	Hard to reclaim	0.50
25E:							
Nason	70	Poor		Poor		Poor	
		Too clayey	0.00	Slope	0.00	Slope	0.00
		Low content of organic matter	0.13	Low strength	0.00	Too Clayey	0.00
		Too acid	0.50	Depth to bedrock	0.39	Hard to reclaim	0.50
26C:							
Poindexter	75	Fair		Poor		Fair	
		Droughty	0.01	Depth to bedrock	0.00	Depth to bedrock	0.03
		Depth to bedrock	0.03			Slope	0.63
		Low content of organic matter	0.13			Rock fragments	0.88
26D:							
Poindexter	85	Fair		Poor		Poor	
		Droughty	0.01	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.03	Slope	0.50	Depth to bedrock	0.03
		Low content of organic matter	0.13			Rock fragments	0.88
26E:							
Poindexter	80	Fair		Poor		Poor	
		Droughty	0.01	Depth to bedrock	0.00	Slope	0.00
		Depth to bedrock	0.03	Slope	0.00	Depth to bedrock	0.03
		Low content of organic matter	0.13			Rock fragments	0.88
27C:							
Sequoia	80	Poor		Poor		Poor	
		Too clayey	0.00	Depth to bedrock	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Low strength	0.00	Rock fragments	0.00
		Too acid	0.50	Shrink-swell	0.87	Slope	0.63

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
27D:							
Sequoia	80	Poor		Poor		Poor	
		Too clayey	0.00	Depth to bedrock	0.00	Slope	0.00
		Low content of organic matter	0.13	Low strength	0.00	Too Clayey	0.00
		Too acid	0.50	Slope	0.50	Rock fragments	0.00
28B:							
State	85	Fair		Good		Fair	
		Low content of organic matter	0.02			Too acid	0.60
		Too acid	0.50				
29D:							
Sweetapple	70	Fair		Poor		Poor	
		Droughty	0.04	Depth to bedrock	0.00	Slope	0.00
		Too sandy	0.10	Slope	0.50	Too sandy	0.10
		Low content of organic matter	0.13			Depth to bedrock	>0.99
29E:							
Sweetapple	70	Fair		Poor		Poor	
		Droughty	0.04	Depth to bedrock	0.00	Slope	0.00
		Too sandy	0.10	Slope	0.00	Too sandy	0.10
		Low content of organic matter	0.13			Depth to bedrock	>0.99
30B:							
Tatum	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.07	Too acid	0.88
		Too acid	0.32	Shrink-swell	0.87	Hard to reclaim	0.92
30C:							
Tatum	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.07	Slope	0.63
		Too acid	0.32	Shrink-swell	0.87	Too acid	0.88
30D:							
Tatum	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Slope	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.07	Too Clayey	0.00
		Too acid	0.32	Slope	0.50	Too acid	0.88

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
31B:							
Thurmont	75	Fair		Poor		Poor	
		Low content of organic matter	0.13	Low strength	0.00	Hard to reclaim	0.00
		Too acid	0.32			Rock fragments	0.88
						Too acid	0.88
31C:							
Thurmont	80	Fair		Poor		Poor	
		Low content of organic matter	0.13	Low strength	0.00	Hard to reclaim	0.00
		Too acid	0.32			Slope	0.63
						Rock fragments	0.88
31D:							
Thurmont	70	Fair		Poor		Poor	
		Low content of organic matter	0.13	Low strength	0.00	Slope	0.00
		Too acid	0.32	Slope	0.50	Hard to reclaim	0.00
						Rock fragments	0.88
32A:							
Toccoa	70	Fair		Good		Good	
		Low content of organic matter	0.13				
		Too acid	0.84				
Frequently flooded	5	Not Rated		Not Rated		Not Rated	
33B:							
Turbeville	80	Poor		Fair		Poor	
		Too clayey	0.00	Low strength	0.22	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Too acid	0.88
		Too acid	0.50				
33C:							
Turbeville	75	Poor		Fair		Poor	
		Too clayey	0.00	Low strength	0.22	Too Clayey	0.00
		Low content of organic matter	0.13	Shrink-swell	0.89	Slope	0.63
		Too acid	0.50			Too acid	0.88
33D:							
Turbeville	70	Poor		Fair		Poor	
		Too clayey	0.00	Low strength	0.22	Slope	0.00
		Low content of organic matter	0.13	Slope	0.50	Too Clayey	0.00
		Too acid	0.50	Shrink-swell	0.89	Too acid	0.88
34B:							

Table ENG-2. - Construction Materials - Continued

Bedford County, Virginia

Map Symbol and Soil Name	Pct of Map Unit	Potential Source of Reclamation Material		Potential Source of Roadfill		Potential Source of Topsoil	
		Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value	Rating Class and Limiting Features	Value
34B:							
Vance	80	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.00	Too acid	0.88
		Too acid	0.32	Shrink-swell	0.90		
34C:							
Vance	75	Poor		Poor		Poor	
		Too clayey	0.00	Low strength	0.00	Too Clayey	0.00
		Low content of organic matter	0.13	Depth to bedrock	0.00	Slope	0.63
		Too acid	0.32	Shrink-swell	0.90	Too acid	0.88
35D:							
Wateree	75	Fair		Poor		Poor	
		Droughty	0.07	Depth to bedrock	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.50	Too acid	0.76
		Too acid	0.50			Depth to bedrock	>0.99
35E:							
Wateree	75	Fair		Poor		Poor	
		Droughty	0.07	Depth to bedrock	0.00	Slope	0.00
		Low content of organic matter	0.13	Slope	0.00	Too acid	0.76
		Too acid	0.50			Depth to bedrock	>0.99
W:							
Water	100	Not Rated		Not Rated		Not Rated	